

| REDUCTION MATRIX                                 | AutoBorne Sealers                | Auto Air Colors                              |                                   | candy <sub>2</sub> O               | Illustration Colors & Wicked Colors |
|--|----------------------------------|--|-----------------------------------|------------------------------------|-------------------------------------|
|  |                                  | Transparents<br>Semi-Opagues<br>Fluorescents | Pearls<br>Aluminums<br>Metallics  |                                    |                                     |
| Full Size<br>Spray Gun<br>1.2mm tip<br>27-30 psi | 1.4mm tip 22-24 psi<br>4012: 10% | 4030: 25%<br>4011/4012: 5-10%                | 4030: 10-25%<br>4011/4012: 5-10%  | 4030: 100-200%<br>4011: 10-20%     | 4030: 25%<br>4011/4012: 5-10%       |
| Mini-Gun<br>0.8 - 1.0mm tip<br>27-30 psi         | 1.2mm tip 22-24 psi<br>4012: 10% | 4030: 25%<br>4011/4012: 10-20%               | 4030: 10-25%<br>4011/4012: 5-10%  | 4030: 50-100%<br>4011: 5-10%       | 4030: 25%<br>4011/4012: 10-20%      |
| Large Tip Size<br>Airbrush<br>30+ psi            | 4012: 25%                        | 4030: 25%<br>4011/4012: 10-20%               | 4030: 10-25%<br>4011/4012: 20-30% | 4030: 50-100%<br>4011/4012: 5-20%  | 4030: 25%<br>4011/4012: 10-20%      |
| Small Tip Size<br>Airbrush<br>Low psi            | Not Recommended                  | 4030: 25%<br>4011/4012: 25-50%               | Not Recommended                   | 4030: 50-100%<br>4011/4012: 10-30% | 4030: 25%<br>4011/4012: 25-50%      |

Seeding – Spray gun: candy<sub>2</sub>O's dyes can seed when thinned with 4012 as opposed to 4011. Use of 4011 instead of 4012 prevents conglomeration of dyes, as does a generous mix of 4030 with candy<sub>2</sub>O. 4011 is best used in conditions over 80°F (27°C). See Technical Data Sheet – creatextech.com for more information.



candy<sub>2</sub>O



CREATEX  
ILLUSTRATION  
COLORS

